Id	Comments	Lat/Long
1	Leaking Pipe	41 17.055/-123 48.545
2	Fence Repair	41 16.939/-123 48.493
3	Pull crossing	41 18.62286/-123 48.23706
4	Pull crossing	41 18.4898/-123 48.6069
5	n/a	41 18.8029/-123 48.50488
6	brush crossing	41 18.36855/-123 49.10206
7	brush crossing	41 18.37443/-123 49.16521
8	brush crossing	41 18.37011/-123 49.09465
9	Clean crossing w/handcrew	41 18.47665/-123 48.98357
10	Clean crossing w/handcrew	41 18.48827/-123 48.95523
11	Clean crossing w/handcrew	41 18.48409/-123 48.89275
12	Clean crossing w/handcrew	41 18.47568/-123 48.79694
13	dip seep	

FSR_type

- Dozer: dips/berms; Grader
- Grader
- Waterbar handlines
- Waterbars

Suppression Repair Point

- Water, Grade, WB
- Used; No Repair Needed
- Excavator: Pull back/WB

DP-5
Block
Block
Block access to dozer areas between these two points
Spread/Smooth Berms
Block
Block
Block
Block
Block
Block
Mulch w/brush
Hand WB
DP-4
DP-7
DP-6
DP-3
DP-2
DP-1
H-1
Div K
Div C
Div X
Div Z
Div Y
Div A
Cable Dip
Pecwan
Pecwan Creek Rd
Surgone
Knuthkotm Cr
Martins Flat
Cappell Flat
McKinnon Hill Rd
Gibbens Rd
Ramstead Rd
Cappell Rd
T11N R3E
T10N R3E
Miles 0 0.375 0.75

Division	Completed Dozer Line
Helispot	Completed Line
Water Source	H - H Hand Line
Yurok Cultural Area	R - R Road as Completed Line
	Proposed Dozer Line
	Yurok Cultural Trail
	Highway
	Dirt Road
	Unimproved Road
	Bureau of Indian Affairs
	USDA Forest Service
	Private
	Yurok Tribal Lands
	Yurok Parcels

Tulley Incident
CA-HUU-006956
Final
599 Acres

Suppression Repair Map

1:24,000
Team 3 GIS
NAD 83