# Suppression Repair
# Kaniksu Complex
# WA-COF-001302
# September 14, 2015

0 0.5 1 Miles

- Hand Line
- Completed Dozer Line
- Completed Line
- Proposed Dozer Line
- Limited Threat - Minimal Action
- <all other values>
- Reopened Road
- Retardant Line
- Hand line
- Repairs Completed
- Repairs Needed

Sullivan Lake
Sullivan Creek
DP-160
Hall Creek
Hall Mountain
Noisy Creek
Fetus Creek
Grease Creek
Pass Creek
Thor Creek
Johns Creek
Gypo Creek
Last Chance Cabin Creek
Grease Creek
Middle Fork Harvey Creek
North Fork Harvey Creek
Harvey Creek
Rocky Fork
Div Onata
Onata Creek
Jungle Creek
South Fork Granite Creek
Reopened Road
Parking Area
DP-167
Seep
Spring seep at west end of dozer line
DP-169
Dozer pushed out spoil for safety zone
Grease Spike/Medivac
placed Gravel
DP-150
hand line
Pullout
Retardant Line
DP-130
N end pushout
Push out across from water near dp120
Water source near DP 120
DP-120
Onata spring seap at end of dozer line
tank
DP-110
special pump intake screen, return to District
DP-101
Onata/Grease Staging
Tillicum Peak
Hall Mountain
Sullivan Lake Recreation Trail 504
Lakeshore Trail 540
533
588
Grassy Top National Recreation 503
22
1935
117°17'W 117°16'W 117°15'W 117°14'W 117°13'W 117°12'W 117°11'W 117°10'W 117°9'W
48°50'N 48°49'N 48°48'N 48°47'N 48°46'N 48°45'N 48°44'N 48°43'N