Kettle Complex Renner

WA-COF-001264

OPS Repair Map
Div W

September 17, 2015
13,799 acres
Perimeter as of 09/16/15 @ 1530

Thursday Weather
Upper Elev 48-55 Deg
Lower Elev 55-64 Deg
RH Upper Elev 55-60%
RH Lower Elev 50-55%
SSW 5-8 Gusts 15 mph

Aerial Hazard
Drop Point
Safety Zone
Helispot
Water Source
Repair Approved
Repair Complete
Repair Needed
Special Needs
Repair Approved, Dozer Line
Repair Complete, Dozer Line
Repair Needed, Dozer Line
Repair Approved, Improved Road
Repair Needed, Improved Road
Repair Needed, Hand Line
Repair Needed, Creek Damage

Div W
DP-240
Hodgson Dip
Branch II
Gallo Springs Helibase
H-40
Gel Dip Site
H-41
Div Z
Div Y
H-42
DP-222
DP-200
DP-230
H-43
DP-205