## SITUATION INFORMATION DEBRIEF FORM

| | | DATE: | TIME: |
|---|---|---|---|
| | | 7-24-17 | 1740 |
| NAME: TOROSIAN + COWINS | POSTION: FOBS | ASSIGNMENT: | PHONE NUMBER: 559-2969-9772 |

#1 ROAD USED AS CONTINGENCY LINE + NO DOZER IMPROVEMENTS FROM VIEWPOINT

#2 REMOVE END OF DOZER LINE DOES NOT CONNECT TO RIVER

#3 REMOVE DOZER LINE - DOZER LINE GOES TO THE EAST

#4 ADJUST HANDLINE TO N/NE

#5 ALL DOZER LINE EXCEPT #6 IS 10 TO 12 BLADES WIDE

#6 ADDED DOZER LINE - 6 BLADE WIDE

#7 SAFETY ZONE - SAFETY WAS IN THE AREA AND MAY HAVE APPROVED IT

#8 POSSIBLE SAFETY ZONE

MEMBER:




N
W E
S

Division
Branch

Drop Point
Uncontrolled Fire Edge
Completed Dozer Line
Proposed Dozer Line

# FOBS MAP

**Detwiler Incident**

CA MMU 014474

July 21, 2017

0 0.325 0.65 1.3 1.95 2.6

Miles