



Repair Status

Repair Points

Approved

Completed

Needed

Not Needed

Needed Repair

Completed Repair

Approved Repair

Not Needed Repair

Aerial Retardant Drop

Completed Dozer Line

Hand Line

Plow Line

Aerial Retardant Drop

Completed Dozer Line

Hand Line

Plow Line

Aerial Retardant Drop

Completed Dozer Line

Hand Line

Plow Line

Aerial Retardant Drop

Completed Dozer Line

Hand Line

Plow Line

Sutherland Canyon and Straight Hollow Fire

WA-SPD-000121  
WA-SPD-000126

Repair Plan Map

07/03/2017  
Day Shift

Perimeter as of 07/02/2017 @ 1200

1

Miles

Map of Washington State

Location of Sutherland Canyon and Straight Hollow Fire

Magnetic Declination: +15.33° E

N

NWIMT11

QR Code

Division

Structures

Town & City Locations

Transmission Line

Railroads

Milepost Markers (DOT)

Highway

Roads (DNR)

DNR Lands

City or Municipality

County

Other

State University

US Bureau of Land Management

US Bureau of Reclamation

US Fish and Wildlife Service

WA Dept of Fish and Wildlife

Point #	Point Type	Lat	Long	Comments	Status
1	Fence Cut	47.344338	-119.764436	none	Needed
2	Fence Cut	47.344291	-119.767182	none	Needed
3	Fence Cut	47.346464	-119.775636	none	Needed
4	Fence Cut	47.347244	-119.779045	none	Needed
5	Fence Cut	47.348255	-119.833184	none	Needed
6	Fence Cut	47.337016	-119.774575	none	Needed
7	Fence Cut	47.333336	-119.829923	none	Needed
8	Fence Cut	47.322413	-119.87855	none	Needed
9	Drop Point	47.356187	-119.972595	DP-3	Needed
10	Drop Point	47.324466	-119.777226	DP-60	Needed
11	Drop Point	47.317384	-119.875762	DP-61	Needed
12	Drop Point	47.417908	-120.048182	DP-20	Needed
13	Drop Point	47.373257	-120.05539	DP-15	Needed
14	Riparian Damage	47.316554	-119.8777	Retardant in Riparian	Needed
15	Fence Cut	47.442326	-119.984741	none	Approved
16	Fence Cut	47.262296	-119.953759	none	Needed
17	Fence Cut	47.310435	-119.886642	none	Needed
18	Fence Cut	47.309135	-119.891539	none	Needed
19	Fence Cut	47.287446	-119.943086	none	Needed