

PHOTOS - OPERATIONS



Dozer line damage repaired



Fire damaged bridge replaced with low water crossing



Fire damaged fence



Fire damaged safety signs



Fire suppression dozer line



Retardant at fire perimeter